ERROR AND MEASUREMENT



point are not significant.

Get More Learning Materials Here : 📕





3. Permissible Error

 Max permissible error in a measured quantity = least count of the measuring instrument and if nothing is given about least count then Max permissible error = place value of the last number

then $(\Delta f)_{max}$ = max of $(\pm \Delta X \pm \Delta Y)$ • f(x,y) = x + y

• f (x,y,z) = (constant) x^a y^b z^c then
$$\left(\frac{\Delta f}{f}\right)_{max}$$

= max of
$$\left(\pm a \frac{\Delta x}{x} \pm b \frac{\Delta y}{y} \pm c \frac{\Delta z}{z}\right)$$

Errors in averaging 4.

• Absolute Error
$$\Delta a_n = |a_{mean} - a_n|$$

• Mean Absolute Error $\Delta a_{mean} = \left(\sum_{i=1}^{n} |\Delta a_i| \right) / n$

• Relative error =
$$\frac{\Delta a_{\text{mean}}}{a_{\text{mean}}}$$

• Percentage error =
$$\frac{\Delta a_{mean}}{a_{mean}} \times 100$$

5. Experiments

 Reading of screw gauge Thicknes of object = Reading of screw gauge

 $= \begin{pmatrix} main \\ scale \\ reading \end{pmatrix} + \begin{pmatrix} circular \\ scale \\ reading \end{pmatrix} \begin{pmatrix} Least \\ count \end{pmatrix}$

pitch

least count of screw gauge = $\frac{\text{pitch}}{\text{No. of circular scale division}}$

- Vernier callipers
- Thicknes of object = Reading of vernier calliper

 $= \begin{pmatrix} main \\ scale \\ reading \end{pmatrix} + \begin{pmatrix} vernier \\ scale \\ reading \end{pmatrix} \begin{pmatrix} Least \\ count \end{pmatrix}$

Least count of vernier calliper = 1 MSD – 1 VSD

Page # 81

>>

