# METALLURGY

The compound of a metal found in nature is called a mineral. The minerals from which metal can be economically and conveniently extracted are called **ores**. An ore is usually contaminated with earthy or undesired materials known as gangue.

- (a) Native ores contain the metal in free state. Silver, gold, platinum etc, occur as native ores.
- (b) Oxidised ores consist of oxides or oxysalts (e.g. carbonates, phosphates, sulphates and silicates ) of metals.
- (c) Sulphurised ores consist of sulphides of metals like iron, lead, zinc, mercury etc.
- (d) Halide ores consist of halides of metals.

Metal	Ores	Composition	
Aluminium	Bauxite	$AIO_X(OH)_{3-2X}$ [where 0 < X < 1] $AI_2O_3$	
	Diaspore	Al <sub>2</sub> O <sub>3</sub> .H <sub>2</sub> O	
	Corundam	Al <sub>2</sub> O <sub>3</sub>	
	Kaolinite (a form of clay)	[Al <sub>2</sub> (OH) <sub>4</sub> Si <sub>2</sub> O <sub>5</sub> ]	
Iron	Haematite	Fe <sub>2</sub> O <sub>3</sub>	
	Magnetite	Fe <sub>3</sub> O <sub>4</sub>	
	Siderite	FeCO <sub>3</sub>	
	Iron pyrite	FeS <sub>2</sub>	
	Limonite	Fe <sub>2</sub> O <sub>3</sub> .3H <sub>2</sub> O	
Copper	Copper pyrite	CuFeS <sub>2</sub>	
	Copper glance	Cu <sub>2</sub> S	
	Cuprite	Cu <sub>2</sub> O	
	Malachite	CuCO <sub>3</sub> .Cu(OH) <sub>2</sub>	
	Azurite	2CuCO <sub>3</sub> .Cu(OH) <sub>2</sub>	
Zinc	Zinc blende or Sphalerite	ZnS	
	Calamine	ZnCO <sub>3</sub>	
	Zincite	ZnO	
Lead	Galena	PbS	
	Anglesite	PbSO <sub>4</sub>	
	Cerrusite	PbCO <sub>3</sub>	
Magnesium	Carnallite	KCI.MgCl <sub>2</sub> 6H <sub>2</sub> O (K <sub>2</sub> MgCl <sub>4</sub> .6H <sub>2</sub> O)	
	Magnesite	MgCO <sub>3</sub>	
	Dolomite	MgCO <sub>3</sub> CaCO <sub>3</sub>	
	Epsomsalt (Epsomite)	MgSO <sub>4</sub> 7H <sub>2</sub> O	
	Langbeinite	K <sub>2</sub> Mg <sub>2</sub> (SO <sub>4</sub> ) <sub>3</sub>	
Tin	Cassiterite (Tin stone)	SnO <sub>2</sub>	
Silver	Silver glance (Argentite)	Ag <sub>2</sub> S	
	Chlorargyrite (Horn silver)	AgCl	

# Metallurgy :

The scientific and technological process used for the extraction/isolation of the metal from its ore is called as metallurgy.

The isolation and extraction of metals from their ores involve the following major steps:

(A) **Crushing and Grinding :** The ore is first crushed by jaw crushers and ground to a powder.

# (B) Concentration :

The removal of unwanted useless impurities from the ore is called **dressing**, **concentration or benefaction of ore**.

### (i) Hydraulic washing or Gravity separation or Levigation method :

It is based on the difference in the densities of the gangue and ore particles. This method is generally used for the concentration of oxide and native ores.

# (ii) Electromagnetic separation :

It is based on differences in magnetic properties of the ore components. Chromite ore(FeO.Cr<sub>2</sub>O<sub>3</sub>) is separated from non–magnetic silicious impurities and cassiterite ore(SnO<sub>2</sub>) is separated from magnetic Wolframite (FeWO<sub>4</sub> + MnWO<sub>4</sub>).

- (iii) Froth floatation process. This method is commonly used for the concentration of the low grade sulphide ores like galena, PbS (ore of Pb); copper pyrites  $Cu_2S.Fe_2S_3$  or  $CuFeS_2$  (ore of copper); zinc blende, ZnS (ore of zinc) etc., and is based on the fact that gangue and ore particles have different degree of wettability with water and pine oil; the gangue particles are preferentially wetted by water while the ore particles are wetted by oil. In this process one or more chemical frothing agents are added.
- (iv) Leaching : Leaching is often used if the ore is soluble in some suitable solvent, e.g., acids, bases and suitable chemical reagents.

# (C) Extraction of crude metal from concentrated ore :

The isolation of metals from concentrated ore involves two major steps as given below.

### (i) Conversion to oxide :

**Calcination.** It is a process of heating the concentrated ore strongly in a limited supply of air or in the absence of air. The process of calcination brings about the following changes :

(a) The carbonate ore gets decomposed to form the oxide of the metal.

(b) Water of crystallisation present in the hydrated oxide ore gets lost as moisture.

(c) Organic matter, if present in the ore, gets expelled and the ore becomes porous. Volatile impurities are removed.



# **Roasting:**

It is a process of heating the concentrated ore (generally sulphide ore) strongly in the excess of air or  $O_2$  below its melting point. Roasting is an exothermic process once started it does not require additional heating.

## Smelting :

**Slag formation :** In many extraction processes, an oxide is added deliberately to combine with other impurities and form a stable molten phase immiscible with molten metal called a slag. The process is termed smelting.

The principle of slag formation is essentially the following : Nonmetal oxide (acidic oxide) + Metal oxide (basic oxide)  $\longrightarrow$  Fusible (easily melted) slag

Removal of unwanted basic and acidic oxides: For example, FeO is the impurity in extraction of Cu from copper pyrite.

$$\begin{array}{ccc} 2\text{CuFeS}_2 + 4\text{O}_2 & \longrightarrow & \text{Cu}_2\text{S} + 2\text{FeO} & + & 3\text{SO}_2\\ \text{Cu}_2\text{S} & + & \text{FeO} & + & \text{SiO}_2\\ & & & & & \text{(roasted pyrite)}^2 \end{array} \xrightarrow{} & \text{FeSiO}_3 \left( \begin{array}{c} \text{Fusible slag} \right) & + & \begin{array}{c} \text{Cu}_2\text{S} \left( \text{matte} \right) \\ & & & & (\text{lower layer}) \end{array} \right)$$

Matte also contains a very small amount of iron(II) sulphide.

To remove unwanted acidic impurities like sand and  $P_4O_{10}$ , smelting is done in the presence of limestone.

 $CaCO_3 \longrightarrow CaO + CO_2$   $CaO + SiO_2 \longrightarrow CaSiO_3$  (fusible slag)  $6CaO + P_4O_{40} \longrightarrow 2Ca_3(PO_4)_2$  (fusible slag - Thomas slag)

# (ii) Reduction of a metal oxide :

The free metal is obtained by reduction of a compound, using either a chemical reducing agent or electrolysis.

# Chemical reduction method :

### Reduction with carbon :

 $PbO + C \longrightarrow Pb + CO$  (extraction of lead)

**Reduction with CO :** In some cases CO produced in the furnace itself is used as a reducing agent.

 $Fe_2O_3 + 3CO \longrightarrow 2Fe + 3CO_2$ 

# Reduction by other metals :

Metallic oxides (Cr and Mn) can be reduced by a highly electropositive metal such as aluminium that liberates a large amount of energy (1675 kJ/mol) on oxidation to  $AI_2O_3$ . The process is known as Goldschmidt or

aluminothermic process and the reaction is known as thermite reaction.  $Cr_{2}O_{3}$  + Al  $\rightarrow$  2Cr ( $\ell$ ) + Al\_{2}O\_{3}

**Magnesium reduction method :** Magnesium is used in similar way to reduce oxides. In certain cases where the oxide is too stable to reduce, electropositive metals are used to reduce halides.

 $TiCI_{4} + 2 Mg \xrightarrow{Krollprocess} Ti + 2 MgCI_{2}$  $TiCI_{4} + 4Na \xrightarrow{IMI \ process} Ti + 4 NaCI$ 

#### Self-reduction method :

This method is also called auto-reduction method or air reduction method. If the sulphide ore of some of the less electropositive metals like Hg, Cu, Pb, Sb, etc. are heated in air, a part of these is changed into oxide or sulphate then that reacts with the remaining part of the sulphide ore to give its metal and SO<sub>2</sub>.

$$Cu_2S + 3O_2 \longrightarrow 3Cu_2O + 2SO_2$$
$$2Cu_2O + Cu_2S \longrightarrow 6Cu + SO_2$$

### Electrolytic reduction :

It presents the most powerful method of reduction and gives a very pure product. As it is an expensive method compared to chemical methods, it is used either for very reactive metals such as magnesium or aluminum or for production of samples of high purity.

- In aqueous solution : Electrolysis can be carried out conveniently and cheaply in aqueous solution that the products do not react with water. Copper and zinc are obtained by electrolysis of aqueous solution of their sulphates.
- 2. In fused melts : Aluminum is obtained by electrolysis of a fused mixture of Al<sub>2</sub>O<sub>3</sub> and cryolite Na<sub>3</sub>[AIF<sub>6</sub>].

Extraction of Aluminium : It involves the following processes (a) Purification of bauxite :

		(iii) Serpeck's Method (used for white bauxite containing silica as impurities) $AI_2O_3 \cdot 2H_2O + 3C + N_2 \xrightarrow{1800^\circ C}$ $2AIN + 3CO + 2H_2O$ $2AIN + 3H_2O \rightarrow AI(OH)_3 \downarrow + NH_3$ $SIO_2 + 2CO \rightarrow 2CO_2 + SI$ Silicone volatilises at this temp. $2AI(OH)_3 \xrightarrow{1473K \Delta} AI_2O_3 + 3H_2O$
--	--	---

**CLICK HERE** 

>>

### (b) Electrolytic reduction (Hall-Heroult process) :

 $\begin{array}{rcl} 2\text{Al}_2\text{O}_3 + 3\text{C} & \longrightarrow & 4\text{Al} + 3\text{CO}_2\\ \text{Cathode}: & & \text{Al}^{3+} & (\text{melt}) + 3\text{e}^- & \longrightarrow & \text{Al(I)}\\ \text{Anode}: & & & \text{C(s)} + \text{O}^{2-} & (\text{melt}) & \longrightarrow & \text{CO(g)} + 2\text{e}^{-1} \end{array}$ 

 $C(s) + 2O^{2-} (melt) \longrightarrow CO_2(g) + 4e^{-}$ 

# Metallurgy of some important metals

# 1. Extraction of iron from ore haematite : Reactions involved :

At 500 – 800 K (lower temperature range in the blast furnace)

 $3 \operatorname{Fe}_2 \operatorname{O}_3 + \operatorname{CO} \longrightarrow 2 \operatorname{Fe}_3 \operatorname{O}_4 + \operatorname{CO}_2$  $\operatorname{Fe}_3 \operatorname{O}_4 + \operatorname{CO} \longrightarrow 3\operatorname{Fe} + 4 \operatorname{CO}_2$ 

 $Fe_2O_3 + CO \longrightarrow 2FeO + CO_2$ At 900 – 1500 K (higher temperature range in the blast furnace):

 $C + CO_2 \longrightarrow 2 CO$ ; FeO + CO  $\longrightarrow$  Fe + CO<sub>2</sub> Limestone is also decomposed tom CaO which removes silicate impurity of the ore as slag. The slag is in molten state and separates out from iron.

 $CaCO_3 \longrightarrow CaO + CO_2$ ;  $CaO + SiO_2 \longrightarrow CaSiO_3$ 

#### Extraction of copper : From copper glance / copper pyrite (self reduction) :

 $\begin{array}{l} 2\mathsf{CuFeS}_2 + 4\mathsf{O}_2 &\longrightarrow \ \mathsf{Cu}_2\mathsf{S} + 2\mathsf{FeO} + 3\mathsf{SO}_2\\ \mathsf{Cu}_2\mathsf{S} + \mathsf{FeO} + \mathsf{SiO}_2 &\longrightarrow \mathsf{FeSiO}_3 \ (\mathsf{fusible slag}) + \mathsf{Cu}_2\mathsf{S} \ (\mathsf{matte})\\ 2\mathsf{FeS} + 3\mathsf{O}_2 &\longrightarrow 2\mathsf{FeO} + 2\mathsf{SO}_2 \quad ; \quad \mathsf{FeO} + \mathsf{SiO}_2 &\longrightarrow \mathsf{FeSiO}_3\\ 2\mathsf{Cu}_2\mathsf{S} + 3\mathsf{O}_2 &\longrightarrow 2\mathsf{Cu}_2\mathsf{O} + 2\mathsf{SO}_2 \ ;\\ 2\mathsf{Cu}_2\mathsf{O} + \mathsf{Cu}_2\mathsf{S} &\longrightarrow \mathsf{6Cu} + \mathsf{SO}_2 \ (\mathsf{self reduction}) \end{array}$ 

# 3. Extraction of lead :

2.

(i) 
$$2PbS(s) + 3O_2(g) \xrightarrow{\Delta} 2PbO(s) \xrightarrow{+C} 2Pb(\ell) + CO_2(g)$$
  
(ii)  $3PbS(s) \xrightarrow{heat in}_{air} PbS(s) + 2PbO(s) \xrightarrow{Heat in}_{absence of air} 3Pb(\ell) + SO_2(g)$ 

## 4. Extraction of zinc from zinc blende :

The ore is roasted in presence of excess of air at temperature 1200 K.

 $2 \text{ZnS} + 30_2 \longrightarrow 2 \text{ZnO} + 2\text{SO}_2$ 

The reduction of zinc oxide is done using coke.

 $ZnO + C \xrightarrow{Coke, 1673K} Zn + CO$ 

## 5. Extraction of tin from cassiterite :

The concentrated ore is subjected to the electromagnetic separation to remove magnetic impurity of Wolframite.

 $SnO_2$  is reduced to metal using carbon at 1200–1300°C in an electric furnace. The product often contains traces of Fe, which is removed by blowing air through the molten mixture to oxidise FeO which then floats to the surface.

# 6. Extraction of Magnesium :

### From Sea water (Dow's process) :

Sea water contains 0.13% magnesium as chloride and sulphate. It involves following steps.

(a) Precipitation of magnesium as magnesium hydroxide by slaked lime.

(b) Preparation of hexahydrated magnesium chloride.

The solution on concentration and crystallisation gives the crystals of MgCl<sub>2</sub>.6H<sub>2</sub>O.

(c) Preparation of anhydrous magnesium chloride.

(d) Electrolysis of fused anhydrous MgCl<sub>2</sub> in presence of NaCl.

 $MgCl_2 \longrightarrow Mg^{2+} + 2Cl^-$ 

At cathode :  $Mg^{2+} + 2e^{-} \longrightarrow Mg(99\% \text{ pure})$ ;

At anode :  $2CI^{-} \longrightarrow CI_{2} + 2e^{-}$ 

Extraction of gold and silver (MacArthur-Forrest cyanide process):
 (a) From native ores : Extraction of gold and silver involves leaching the metal with CN<sup>-</sup>.

4Au / Ag (s) + 8CN<sup>-</sup>(aq) + 2H<sub>2</sub>O(aq) + O<sub>2</sub>(g)  $\longrightarrow$  4[Au / Ag (CN)<sub>2</sub>]<sup>-</sup>(aq) + 4OH–(aq)

 $2[Au / Ag (CN)_2]^{-}(aq) + Zn(s) \longrightarrow 2Au / Ag (s) + [Zn(CN)_4]^{2-}(aq)$ 

# (b) From argentite ore :

 $\begin{array}{l} \text{Ag}_2\text{S} (\text{conc. ore}) + 2\text{NaCN} & \xrightarrow{\text{Air}} 2\text{AgCN} + \text{Na}_2\text{S}. \\ 4\text{Na}_2\text{S} + 5\text{O}_2 + 2\text{H}_2\text{O} & \longrightarrow 2\text{Na}_2\text{SO}_4 + 4\text{NaOH} + 2\text{S} \\ \text{AgCN} + \text{NaCN} & \longrightarrow \text{Na}[\text{Ag}(\text{CN})_2] (\text{soluble complex}) \\ 2\text{Na}[\text{Ag}(\text{CN})_2] + \text{Zn} (\text{dust}) & \longrightarrow 2\text{Ag} \downarrow + \text{Na}_2[\text{Zn}(\text{CN})_4]. \end{array}$ 

# (D) Purification or Refining of metals :

**Physical methods :** These methods include the following processes: (I) Liquation process : This process is used for the purification of the metal, which itself is readily fusible, but the impurities present in it are not, used for the purification of Sn and Zn, and for removing Pb from Zn-Ag alloy.

(II) Fractional distillation process : This process is used to purify those metals which themselves are volatile and the impurities in them are nonvolatile and vice-versa. Zn, Cd and Hg are purified by this process.

(III) Zone refining method (Fractional crystallisation method) : This process is used when metals are required in very high purity, for specific application. For example pure Si and Ge are used in semiconductors

Chemical methods : These methods include the following methods:

# (I) OXIDATIVE REFINING :

This method is usually employed for refining metals like Pb, Ag, Cu, Fe, etc. In this method the molten impure metal is subjected to oxidation by various ways.

### (II) POLING PROCESS :

This process is used for the purification of copper and tin which contains the impurities of their own oxides.

Green wood  $\rightarrow$  Hydrocarbons  $\rightarrow$  CH<sub>4</sub> 4CuO + CH<sub>4</sub>  $\rightarrow$  4Cu (pure metal) + CO<sub>2</sub> + 2H<sub>2</sub>O

### (III) ELECTROLYTIC REFINING :

Some metals such as Cu, Ni, and AI are refined electrolytically.

### (IV) VAPOR PHASE REFINING :

### (i) Extraction of Nickel (Mond's process) : The sequence of reaction is

### (ii) Van Arkel–De Boer process :

Impure Ti + 2I<sub>2</sub>  $\xrightarrow{50-250^{\circ}C}$  TiI<sub>4</sub>  $\xrightarrow{1400^{\circ}C}$  Ti + 2I<sub>2</sub>

